

**Mercedes-Benz New Zealand
TAKATA Recall and Replacement Timetable - Vans**

Stage	Vehicle			Airbag Inflator Family	Tentative start date
	Designation	Model	Model Year	Inflator Type	
1	906	Sprinter Ambulance (Commercial)	2006 - 2017	Driver & passenger side inflator	Dec-18
2	639	Viano & Vito (Domestic)	2006 - 2014	Driver Side inflator	Feb-19
4.1	639	Vito (Commercial)	2006 - 2014	Driver Side inflator	Apr-19
	906	Sprinter other (Commercial)	2006 - 2017	Driver & passenger side inflator	
	906	Sprinter other (Commercial)	2006 - 2013	Driver Side inflator	
4.2	639	Vito (Commercial)	2006 - 2014	Driver Side inflator	Jun-19
	906	Sprinter other (Commercial)	2006 - 2017	Driver & passenger side inflator	
	906	Sprinter other (Commercial)	2006 - 2013	Driver Side inflator	
4.3	639	Vito (Commercial)	2006 - 2014	Driver Side inflator	Aug-19
	906	Sprinter other (Commercial)	2006 - 2017	Driver & passenger side inflator	
	906	Sprinter other (Commercial)	2006 - 2013	Driver Side inflator	
4.4	639	Vito (Commercial)	2006 - 2014	Driver Side inflator	Oct-19
	906	Sprinter other (Commercial)	2006 - 2017	Driver & passenger side inflator	
	906	Sprinter other (Commercial)	2006 - 2013	Driver Side inflator	
4.5	639	Vito (Commercial)	2006 - 2014	Driver Side inflator	Dec-19
	906	Sprinter other (Commercial)	2006 - 2017	Driver & passenger side inflator	
	906	Sprinter other (Commercial)	2006 - 2013	Driver Side inflator	